

FIG. 1

2/11




FIG. 2

3/11




FIG. 3A




FIG. 3B

5/11




FIG. 3C

6/11





FIG. 4A

$$C_{k, m-1} = \begin{bmatrix} C_{0,0} & C_{0,1} & \cdots & C_{0,m-1} \\ C_{1,0} & & & \\ C_{2,0} & & & \\ \vdots & & & \\ C_{k,0} & & & C_{k,m-1} \end{bmatrix}$$

FIG. 4B


7/11



PSK FAST HADAMARD TRANSFORM

FIG. 5

9/11



10/11




FIG. 7B

11/11

800 ↗




FIG. 8